U. S. Post Office Highway 85 Grassy Butte McKenzie County North Dakota

HABS MO 27-GRABU

## **PHOTOGRAPHS**

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey National Park Service Department of the Interior Washington, D.C. 20240 Form 10-920 (June 1983)

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

MD ND 27-GRABU

## ARCHITECTURAL DATA FORM

STATE	COUNTY		TOWN OR VICINITY	
North Dakota	th Dakota McKenzie		Grassy Butte	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)			<del></del>	HABS NO.
U. S. Post Office			ND-19	
SECONDARY OR COMMON NAMES OF STRUCTURE				
COMPLETE AODRESS (DESCRIBE LOCATION FOR RURAL SITES)				
Highway 85				
DATE OF CONSTRUCTION (INCLUDE SOURCE)		ARCHITECT(S) (INCLUDE SOURCE)		
1914		Tom and Jim Marucheck, builders		
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)				
Built by pioneer settlers in the small community of Grassy Butte. Logs hauled by John Hoffman and others, laid by John Marucheck, plastered by Carl Jagol, who				
learned his trade in Russia. First postmasters were Don McKenzie and his wife until				
1947, and then their daughter until 1963. STYLE (IF APPROPRIATE)				
AAATERIAL OF CONSTRUCTION (INCLUDE CTOLICTURAL SVETENS)				
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)  Cedar logs plastered over with a mixture of qumbo, straw, cement, and water.				
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)				
One story, 19' x 31'-6"				
EXTERIOR FEATURES OF NOTE				
Original roof: two 10"-round cottonwood logs are supported by two cross rafters.				
Roofing was 3"-round or 3" deep split logs running from two parallel ridge poles,				
with a layer of building paper, hay, and clay, topped with scoria.				
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)				
	<u> </u>	· · · · · · · · · · · · · · · · · · ·		
MAJOR ALTERATIONS AND ADDITIONS WITH DATES				
1968: Roof rebuilt. Two new ridge logs covered with tin roofing which is covered by dirt and topped by scoria. New concrete floor, extending 3' on three sides of the building.				
PRESENT CONDITION AND USE				
OTHER INFORMATION AS APPROPRIATE				
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)				
Inventory forms by Charles S. Pope, HABS, September, 1961; and Raymond Fleck,				
President, Grassy Butte Chapter of McKenzie County Museum and Historical Society, ca. 1968.				
COMPILER, AFFILIATION				DATE
Alison K. Hoagland, HABS			October, 1984	